

NOTE: In order to prevent arcing that caused pin burned, please make sure the cable connector is push all the way down to screwdriver side before tighten the metal ring.

