Dear Partners,

Recently we got some feedback from customers that SKD-RBN350L with jamming clutch problem under special application.

After we tested and analyzed this issue, Kilews found the problem might be caused by power drop from the power supply.

Therefore, Kilews enhance the power from 800W to 1200W for SKP-40B-HL-800 / BC40HL-800 v3.0 for using with SKD-RBN350L,P & RBN500L,P tools.

The model no and sticker will be kept unchanged, we will add small sticker (red cross) on housing and outer box (see attached file) as identification.

For SKD-BN900/TBN60,90,120,180L/RBN60,90,120,180,250L,P, the power supply are still same as SKP-40B-HL-800 / BC40HL-800 v3.0 (800W).

Thank you for kind attention.

Best Regards,

Loover-Kilews Industrial Co., Ltd.





