

Dear Partners,

The following is the SKP-BC40HL / SKP-BC32HL-100 ( include version 1.0 and 3.0) terminal cover modification change notice:

This modification is for the convenience of user easier to replace with different automation equipment, while connect to PLC.

Please see the attachment for detail information and thank you for your attention on above notice.

Loover-Kilews Industrial Co., Ltd

**SKP-BC 40HL / SKP-BC 32 HL- 100 modify notification  
version)**

**(include 1.0 and 3.0**

The purpose is for the convenience of clients may replace with different automation equipment, while easy to connect with PLC. SKP-BC40HL / SKP-BC32HL-100 original install Part Number C50217 (as shown in a Figure 1 terminal cover) after modify change to part number C50227A (ex: Figure II terminal cover semi-assembled with green male terminal connector) and attach with the E31701-25 green female terminal connector (standard). After finish the counters in the stock (about 30 units), KILEWS will change to the new modify counter. Comparison of new and old type of terminal cover refers to the following:

Figure I (old) terminal cover. Part Number: C50217



Figure II (new) Transfer semi- assembled with green male terminal connector. Part Number: CA50227A

Part



Figure III (new) female terminal connector. Part Number: E31701-25

